

#### Overview

- Introduction
- Examples of recent cases at Hella
- Examples of recent cases at Aumovio
- Inspection methodologies
- Existing Norms and Guidelines
- Conclusions





#### Introduction


- Technical Cleanliness became important for mechanical systems in the automotive world around 2000
- Electronic Components originally were not in the focus
- Semiconductor companies sometimes stated, that Technical Cleanliness is not relevant to them as it was setup for mechanical systems
- They argue with their cleanroom policy (ISO 14644)
- As most particles are process generated and not airborne, this is not sufficient




Hella Case #1









- Plastic Protrusions from mold process
- Non metallic Particles
- Insufficient Cleaning of the Component after Molding



Hella Case #1

#### Evaluation at Hella acc VDA19.1 On virgin parts from reel



Length [µm]	Code	per Filter Membrane		per Part/Component		per 1000 cm <sup>2</sup>	
		Total <sup>2</sup>	Metallic	Total <sup>2</sup>	Metallic	Total <sup>2</sup>	Metallic
Summary:							
> 600	J-N	0	0	0.0	0.0	0.0	0.0
100600	F-I	85	0	1.7	0.0	188.9	0.0
15100	C-E	145	0	2.9	0.0	322.2	0.
Detailed resul	lts:						
> 3000	N	0	0	0.0	0.0	0.0	0.
20003000	M	0	0	0.0	0.0	0.0	0.
15002000	L	0	0	0.0	0.0	0.0	0.
10001500	K.	0	0	0.0	0.0	0.0	0.
8001000	J	0	0	0.0	0.0	0.0	0.
400600	1	0	0	0.0	0.0	0.0	0.
200400	Н	22	0	0.4	0.0	48.9	0.
150200	G	18	0	0.4	0.0	40.0	0.
100150	F	45	0	0.9	0.0	100.0	0.
50100	E	62	0	1.2	0.0	137.8	0.
2550	D	52	0	1.0	0.0	115.6	0.
1525	С	31	0	0.6	0.0	68.9	0.
515	В	198	0	4.0	0.0	440.0	0.



Hella Case #1

Hella Concern: Non metallic Particles might affect solder connection



->Hella requirement : Maximum particle size < 200µm ( HN40001)


Particle size [µm]	class	ZVEI	Supplier	Hella	Hella
		example	measurement	measurement	requirement
600 ≤ x < 1000	J	0	0	0	0
$400 \le x < 600$	l	0	2	0	0
200 ≤ x < 400	Н	32	24	48	0
150 ≤ x < 200	G	60	41	40	no limit
100 ≤ x < 150	F	160	110	100	no limit
50 ≤ x < 100	E	800	680	137	no limit

- -> Currently this is not achieved in the industry
- ->There is no real limit existing




Hella Case #2


- Smaller Particles on the surface of QFN leads
- Caused by scratching of the component, when placing it into the tape
- Insufficient Tolerance between component and tape dimensions
- might cause soldering problems



Hella Case #3









- Black material on QFN Pins
- Origin : Flitters of Tape Material
- Rootcause :

Tolerance between tape width and linear track of testing machine did not match for all tape suppliers

 Usually this would not cause an issue, but...
 ( see next page)







	1		MCHP Edits
ITAC-Fail value	Analyse-SUT	resistance betw. Pin 37 & 38	R as value
[mV]	[mV]	TP 155 - 154, Soll: ca. 8M	MIN=530
limits: -50 ~ 50			MAX=4720
228.37		811k	81
81.27	82,95	2,31M	231
334.78		1,15M	115
165.06	165,09	1,25M	125
121.22	112,94	1,84M	184
145.8		1,51M	151
53.08		4,03M	403
162.59	156,07	1,63M	163
188.87	182,30	1,23M	123
172.92		1,22M	122
106.73		1,94M	194
132.91	105,32	1,77M	177
177.04	178,72	1,26M	126
E0 E2	EE AC	4 7014	470


Here, the application had a sensor input, Where a high resistance (8MOhms) was needed between to adjacent pins

Tape material has a lower resistance than standard isolating plastics due to ESD requirements

This can result in parallel resistors of several 100kOhm, which caused electrical failures



Aumovio Case #4





Escape: The particles were not detected in the lead scan at the supplier due to insufficient contrast. Tightening limits resulted in high over rejection rate.

Foreign material under lead detected by SMT camera before soldering the IC on the PCB board. Increased scrap in test.

Based on detected elements (Si, Fe, others) the supplier identified the Trim & Form process as the most probably source.


Mold debris accumulated at the Trim & Form as the established cleaning frequency was insufficient.





AUMOVIO

### TECHNICAL CLEANLINESS FOR ELCTRONICAL COMPONENTS

Aumovio Case #5







Escape: Bottom inspection not active at the supplier as this was rated as "not feasible" and showed a high over rejection rate. Top side inspection also not very sensitive due to non-optimum lightning condition.

Foreign material contamination observed in device inspection prior to SMT assembly. Same defects observed in multiple units from different material batches.

Worn out tooling in Trim & Form identified as root cause, resulting in accumulation of debris.

Missing PM item resulted in non-detection and replacement of the worn out part of the Trim & Form tool.

Inspection methodologies

Extraction

Filtration

Analysis



Inspection methodologies @Forvia

#### **Standard Particle Monitoring**

(VDA 19 based) Established in every GE production plant



Rinsing Cabinet



Particle Counting Microscope

Particle Filter Conditioning



#### **Advanced Particle Monitoring**

Lippstadt



- IR spectroscope
- CT
- · High precision scales
- XRF (Fischerscope)

Microscopes



Additional rinsing cabinets





VDA Vernand der 19
Quality Management In the Automotive Industry
Inspection of Part 1
Technical Cleanliness

Norms and Guidelines

INTERNATIONAL STANDARD

ISO 16232

> First edition 2018-12

Road vehicles — Cleanliness of components and systems

Véhicules routiers — Propreté des composants et des systèmes

- VDA 19.1 first established in 2004
- International Version established as ISO 16232 in 2018




#### Norms and Guidelines

#### IEC16232 and VDA19.1

- Detailed description of measurement setups
- Extraction methods
  - Liquid
  - Air
- Filtration Methods
- Analysis methods

Fig. 1: Test method as per VDA 19 Part 1





#### Norms and Guidelines

#### IEC16232 and VDA19.1

- Qualification tests and blank value
- Cleanliness Specifications
  - Metallic / Non metallic / Fibres
- Examples
  - Air tank
  - Piston Rings
  - Plastic housings
  - Cast cylinders
  - Crankshaft
    - -> Focus on mechanical components





Guideline

#### Technical Cleanliness in Electrical Engineering

Dirt is simply matter in the wrong place

2nd extended edition



PCB and Electronic Systems Division Electronic Components and Systems Division

#### Norms and Guidelines

- 2018
- Dedicated to Electronics
- Pressure Rinsing
- Metallic / Non metallic / Fibres
- Particle Sources
- Metallic Components vs Shorts
- No limits
- Empirical data for Component classes (that may serve as reference)



#### Norms and Guidelines



Guidelin

#### Technical Cleanliness in Electrical Engineering

Dirt is simply matter in the wrong place

2nd extended edition



PCB and Electronic Systems Division Electronic Components and Systems Division 4.2.2.6 Semiconductors

Table 15: Empirical data from semiconductors

Empirical particle data from semiconductors per 1000 cm² surface, based on particle class					
Particle size [µm]	Size classes	All particles	Metallic particles <sup>1)</sup>		
50 ≤ x < 100	E	8000	100		
100 ≤ x < 150	F	1600	20		
150 ≤ x < 200	G	600	0.00		
200 ≤ x < 400	Н	320	0.00		
400 ≤ x < 600	1	0.00	0.00		
600 ≤ x < 1000	J	0.00	0.00		
1000 ≤ x < 1500	K	0.00	0.00		
1500 ≤ x < 2000	L	0.00	0.00		
2000 ≤ x < 3000	M	0.00	0.00		
3000 ≤ x	N	0.00	0.00		



#### Conclusions

- Hella / Aumovio experienced significant issues with technical cleanliness of supplier electronic components in the last years
- Applicable and established industry standard exist that allow to define cleanliness criteria and specify methods for quantitative evolutions
- Particles adhering to components can cause solderability issues, test rejects and potential latent defects
- Supplier do not specify any cleanliness level of the shipped material
- It needs to be questioned on whether tape material flitters can be handled correctly with the definition of metallic/non metallic
- There is no limits defined in the norms



Conclusions

#### Tier 1 expectation:

- Semiconductor suppliers should monitor their particle count
- Semiconductor suppliers should assure a defined level of cleanliness

